## Oil Field Environmental Incident Summary

Responsible Party: Triangle USA Petroleum Corporation

Well Operator: TRIANGLE USA PETROLEUM CORPORATION

Well Name: J. GARVIN JACOBSON 150-101-8-5-1H

Field Name: PRONGHORN Well File #: 23534

Date Incident: 11/29/2013 Time Incident: Facility ID Number:

County: MCKENZIE Twp: 150 Rng: 101 Sec: 8 Qtr: SE SW

Location Description:

Submitted By: Amber Schaller Received By:

Contact Person: Amber Schaller

1200 17TH ST., SUITE 2600

DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 750 feet

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: Unknown

Spilled Market

	Spillea	Units	Recoverea	Units	
Oil	25	barrels	20	barrels	
Brine	0	barrels	0	barrels	
Other	0	barrels	0	barrels	

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Followup

Units

## Potential Environmental Impacts:

None

## Action Taken or Planned:

Garner Environmental Services, Inc. was contacted, 20 barrels was sucked up with a vac truck. Garner is removing contaminated soil and hauling it to Dishon Disposal. Triangle plans to replace the poly line that ruptured with steal.

Wastes Disposal Location: Dishon Disposal, Inc.

Agencies Involved:

## **Updates**

Date: 12/2/2013 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

According to the report, the incident remained on location. NDIC retains oversight.